COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature: OFFICIAL PARTY AND	Date: 2023-07-17
Conducted by: ORVEINE PAUL/ALMAGRO	
Department: א-אַבּבּאַ פּאָכּאָהָאַפּ PC no. :	
Factory no. : FACTORY 2	
Factory No Thereto 2	
☑ Clean Dust on CPU	
☑ Deleting Temp/Junk Files	
☑ Antivirus Scan	
☑ Disabling Hotspot	
☑ Windows Update(Optional)	
☑ Remove/Uninstall Unwanted Program	
Check Monitor/Screen for Defect	
Ø OK □Not OK	
Check Charger for Defect	
☑ OK □Not OK	
Check Keyboard Casing	
☑ OK □Not OK	
Check Lan Connection	
Ø OK □Not OK	
Check battery life	
□ OK ☑Not OK	
Others:	
Pomindore:	
Reminders: Must bring this following tools to perform the Compute	r Preventive
Maintenance (CPM), the tools are screwdriver, brush	
crimper and RJ45.	i, biowoi, ciasci,
emiper and to to.	

				Related Documents	TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	RETENTION PERIOD
Efectivity Date: 2023-07-15	Prepared by:		Checked by: Approved by:	(0)	
Licourny Date.	2020-07-10	Rushky E	Estrera	Rey Dagatan Amadito Ortizano	10 YEARS