GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
	2017-08-02	
User Signat	ure: janany Date: 10	12 3 - 08 - 02
Conducted	Dy: Marly Sarrys	
Department	Pc	
PC no. : TFX	0514	
Factory no.	Medical factory	
	an Dust on CPU	
	eting Temp/Junk Files	
☐ Ant	ivirus Scan	
	abling Hotspot	
□ Wir	dows Update(Optional)	
□ Rer	nove/Uninstall Unwanted Program	
Check	Monitor/Screen for Defect	
	☐ OK ☐ Not OK	
Check	Charger for Defect	
	OK Not OK	
Check	Keyboard Casing	
	□ OK □ Not OK	
Check	Lan Connection	
	□ OK □Not OK	
Check	battery life	
	☐ OK ☐ Not OK	
Ollera		
Other	S.	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.