GA Division	COMPUTER PREVENTIVE	TMF-G0054
ΙΤ	<b>MAINTENANCE CHECKLIST</b>	Version 1.00
User Signatur Conducted by Department:_ PC no. : Factory no. :_	PR TEXCOLIN	1029 - <sup>0</sup> 0-10
☑ Delet □ Antiv ☑ Disab □ Wind	n Dust on CPU ing Temp/Junk Files irus Scan oling Hotspot ows Update( Optional ) ove/Uninstall Unwanted Program	
Check I Check I	Monitor/Screen for Defect  ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Keyboard Casing ☐ OK ☐ Not OK Lan Connection ☐ OK ☐ Not OK Dattery life ☐ OK ☐ Not OK	
Others:		
	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, 2J45.	Related Documents: TMF-G0058

<sup>\*</sup>It is permitted to use this form in both electronic and hard copy.
\*The user have to check and compare versions, effective date and sub master information before printing.