COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature:	Date: <u>১৯১গ - ৽৪- ৽গ</u>
Conducted by: KNAVEN JADE PARAN	
Department: Γ ^{FXC} ω 26	
PC no.: P.E. Process	
Factory no. : Factory 1	
☑ Clean Dust on CPU	
☐ Deleting Temp/Junk Files	
☐ Antivirus Scan	
☐ Disabling Hotspot	
☑ Windows Update(Optional)	
☐ Remove/Uninstall Unwanted Program	
· ·	
Check Monitor/Screen for Defect	
☐ OK ☐ Not OK	
Check Charger for Defect	
☐ OK ☐Not OK Check Keyboard Casing	
□ OK □Not OK	
Check Lan Connection	
☑ OK □Not OK	
Check battery life	
☑ OK □Not OK	
Others:	
	İ
<u> </u>	
Reminders:	
Must bring this following tools to perform the Com	
Maintenance (CPM), the tools are screwdriver, b crimper and RJ45.	rusii, biower, etaset,
Chimper and 15040.	

2

Checked by:

Rey Dagatan

VER.
Prepared by:

Rushky Estrera

Document No:

Efectivity Date:

TCF-G112

2023-07-15

Related Documents:

Amadito Ortizano

Approved by:

Toyoflex Cebu Corporation

TCF-G116

RETENTION PERIOD

10 YEARS