## **COMPUTER PREVENTIVE MAINTENANCE CHECKLIST**

User Signature:	Date: <u>2023</u> -	02-17
Conducted by: ORVEINE PAUL ALMAGRO		
Department: we- oawne		
PC no. :		
Factory no. : FACTORY 3		
☑ Clean Dust on CPU		
☑ Deleting Temp/Junk Files		
☑ Antivirus Scan		
☑ Disabling Hotspot		
Windows Update( Optional )		
☑ Remove/Uninstall Unwanted Program	n	
Observation ID and a section Defect		
Check Monitor/Screen for Defect		
☑ OK □Not OK		
Check Charger for Defect		
☑ OK □Not OK		
Check Keyboard Casing		
☑ OK □Not OK		
Check Lan Connection		
☑ OK □Not OK		
Check battery life ☑ OK □Not OK		
₩ OK LINGLOK		
Others:		
Others.		
<del>-</del>		
Reminders:		
Must bring this following tools to perform the Co	mputer Preventive	
Maintenance ( CPM ), the tools are screwdriver,	brush, blower, eraser,	
crimper and RJ45.		
	Related Documents:	TCF-G116

2

Checked by:

Rey Dagatan

VER.
Prepared by:

Rushky Estrera

**Toyoflex Cebu Corporation** 

Approved by:

Amadito Ortizano

RETENTION PERIOD

10 YEARS

Document No:

Efectivity Date:

TCF-G112

2023-07-15