COMPUTER PREVENTIVE MAINTENANCE CHECKLIST 2127-07-66 Tecturaling User Signature: Date: 2023-07-17 Conducted by: *Optic 3 MAJUI CHARL Department: TASSY / Production PC no.: TEXCO635 2 Factory no. :_ Factory ☑ Clean Dust on CPU ☑ Deleting Temp/Junk Files ☑ Antivirus Scan □ Disabling Hotspot ■ Disabling Hotsp □-Windows Update(Optional) ☐ Remove/Uninstall Unwanted Program Check Monitor/Screen for Defect ☑ ÓK □Not OK Check Charger for Defect ☐ OK ☐ Not OK **Check Keyboard Casing** ☑ OK ☐ Not OK Check Lan Connection ☐ OK ☑ Not OK Check battery life OK ONOT OK Others: LVL 3

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

				F	Related Documents:	TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation		RETENTION PERIOD
Efectivity Date:	2023-07-15	Prepared by:	Prepared by: Checked by: Approved by:		pproved by:	40.7/24.00
		Rushky Es	trera	Rey Dagatan	Amadito Ortizano	10 YEARS