| GA Division | COMPUTER PREVENTIVE | TMF-G0054 |
|--|---|------------------------------|
| IT | MAINTENANCE CHECKLIST | Version 1.00 |
| User Signature Conducted by Department: PC no. : Factory no. : | Date:_ Sytick payrum Alwangur TEXC 0499 | N°14- 08-20 |
| ☑ Delet ☑ Antivi ☑ Disab □ Wind | n Dust on CPU ing Temp/Junk Files frus Scan pling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program | |
| Check b Check L | Monitor/Screen for Defect ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Keyboard Casing ☐ OK ☐ Not OK Lan Connection ☐ OK ☐ Not OK Dattery life ☐ OK ☐ Not OK | |
| Others: | | |
| | s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, J45. | Related Documents: TMF-G0058 |

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.