## **COMPUTER PREVENTIVE MAINTENANCE CHECKLIST**

User Signature:	Date:					
Conducted by: ORVEINE PAUL ALMAGRO						
Department: one Phets Production						
PC no. : TFX coo36						
Factory no.: FACTORY 48						
T. O. D. J. O.D.I.						
☑ Clean Dust on CPU						
☑ Deleting Temp/Junk Files						
☑ Antivirus Scan						
<ul><li>☑ Disabling Hotspot</li><li>☑ Windows Update( Optional )</li></ul>						
01 114 11 10 1 1 10 1						
Check Monitor/Screen for Defect						
☑ OK □Not OK						
Check Charger for Defect						
□ OK □Not OK						
Check Keyboard Casing						
☑ OK □Not OK						
Check Lan Connection						
☑ OK □Not OK						
Check battery life						
□ OK □Not OK						
Other control of the						
Others:						
COMMON PC	İ					
	ł					

## Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TCF-G116					
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	n RETENTION PERIOD
Efectivity Date: 2023-07-15		Prepared by	:	Checked by: Approved by:	10 YEARS
Liectivity Date.	2023-01-13	Rushky	Estrera	Rey Dagatan Amadito Ortiz	