GA Division	COMPUTER PREVENTIVE	E	TMF-G0054
IT	MAINTENANCE CHECKLIS	ST	Version 1.00
Conducted by: Department: м PC no. : rex co Factory no. : м □ Clean □ Deleti	Mario (arrora 120 (0) 120 (0) 124 124 124 124 Dust on CPU ng Temp/Junk Files	Date: 2 023	- br. b7
☑ Disab □ Windo	rus Scan ling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program		
Check Check K	Ionitor/Screen for Defect ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Ceyboard Casing ☐ OK ☐ Not OK an Connection ☐ OK ☐ Not OK attery life ☐ OK ☐ Not OK		
Others:			

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.