## COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

2012-07-17 User Signature: Conducted by: Suspine Department: T-ASSU OFFICE TF400635 PC no.:

Date: 1027-01-17

- Clean Dust on CPU
- ☑ Deleting Temp/Junk Files

FACTORY 2

☑ Antivirus Scan

Factory no.:\_\_\_

- ☑ Disabling Hotspot
- ☑ Windows Update( Optional )
- ☑ Remove/Uninstall Unwanted Program

Check Monitor/Screen for Defect

☑ OK □Not OK

Check Charger for Defect

☑ OK □Not OK

Check Keyboard Casing

☑ OK □Not OK

**Check Lan Connection** 

☑ OK □Not OK

Check battery life

☑ OK □ Not OK

Others: | \* | WE WITH

4 FIREWALL: LEVEL 3

+ SHYLAH MAE FLORECE DOGTE

## Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

		Related Documents:			TCF-G116	
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corpo	oration	RETENTION PERIOD
Efectivity Date:	2023-07-15	Prepared by:		Checked by: Approved by:		
		Rushky	Estrera	Rey Dagatan Amadito Ortizano		10 YEARS