COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

1.20

	User Signature Conducted by: Department: PC no.: 15x	CPP and thor	ARAN		Dat	: e : <u> </u>	<u>- 07 -25</u>
	Factory no. :						
	· dotory no	ц.					
	☑ Deleti ☑ Antivi ☑ Disab ☑ Windo	Dust on CPUng Temp/Junious Scan ling Hotspotows Update(Cove/Uninstall U	k Files Optional)	Program			
	Check (Check K	attery life	INot OK efect INot OK ing INot OK	t			
	Others:						
	.						
Reminders: Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.							
D	T05 5		<u> </u>		Related Documen		TCF-G116
Document No:	TCF-G112	VER. Prepared by:			ou Corporation Approved by:	n RE	TENTION PERIOD
Efectivity Date:	2023-07-15	Rushky Estre		tey Dagatan	Amadito Ortiza	ano	10 YEARS