COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature: Conducted by: Paran, Fram Jalu Department: P.C PC no.: T+XC 06 76	Date: <u>μ21 - 07 - 20</u>
Factory no. : Fred-m 3	
☑ Clean Dust on CPU	
☑ Deleting Temp/Junk Files	
☑ Antivirus Scan	
☑ Disabling Hotspot	
☑ Windows Update(Optional)	
☐ Remove/Uninstall Unwanted Program	
Check Monitor/Screen for Defect ☐ OK ☐ Not OK Check Charger for Defect ☐ OK ☐ Not OK Check Keyboard Casing ☐ OK ☐ Not OK Check Lan Connection ☐ OK ☐ Not OK Check battery life ☐ OK ☐ Not OK	
Others:	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

		***************************************		Related Docume	ents: TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	n RETENTION PERIOD
Efectivity Date: 2023-07-15	2022 07 45	Prepared by:		Checked by: Approved by:	40.74
	Rushky	Estrera	Rey Dagatan Amadito Orti	zano 10 YEARS	