## **COMPUTER PREVENTIVE MAINTENANCE CHECKLIST**

User Signature:	Date:
Conducted by: ORVEINE PAUL ALMAGRO	
Department: FUN	
PC no.: TEXCORG?	
Factory no. : FACTORY 4A	
☑ Clean Dust on CPU	
☑ Deleting Temp/Junk Files	
☑ Antivirus Scan	
☑ Disabling Hotspot	
☑ Windows Update( Optional )	
☑ Remove/Uninstall Unwanted Program	
•	
Check Monitor/Screen for Defect	
☑ OK □Not OK	
Check Charger for Defect	
☑ OK □Not OK	
Check Keyboard Casing	
☑ OK □Not OK Check Lan Connection	
✓ OK □Not OK	
Check battery life	
☑ OK □Not OK	
2011 21101 611	
Others:	
PACL 3	
<u> </u>	

## Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

				Related Documents	: TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	RETENTION PERIOD
Efectivity Date: 2023-07-15	Prepared by	<b>/</b> :	Checked by: Approved by:	10 YEARS	
		Rushky	Estrera	Rey Dagatan Amadito Ortizar	