| GA Division | COMPUTER PREVENTIVE | TMF-G0054 |
|------------------------------------|--|--------------|
| IT | MAINTENANCE CHECKLIST | Version 1.00 |
| Department: No PC no. : 15× | : JT-ANN ARRIBADO 1-PRO | 0023-07-11 |
| ☐ Delet☐ Antivi☐ Disab☐ Wind☐ Remo | ing Temp/Junk Files irus Scan bling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program Monitor/Screen for Defect | |
| Check b | Ø OK □Not OK | |
| Others: | | |

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.
*The user have to check and compare versions, effective date and sub master information before printing.