	GA Division
46.3	

IT

COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

TMF-G0054

Version 1.00

	Jser Signature:	Date: <u>402η-08-02</u>
	Department: ##/#K	
	PC no. : TFX c 0874	
١	actory no. : MEDICAL FACTORY	
	 □ Clean Dust on CPU ☑ Deleting Temp/Junk Files ☑ Antivirus Scan ☑ Disabling Hotspot □ Windows Update(Optional) □ Remove/Uninstall Unwanted Program 	
	Check Monitor/Screen for Defect ☐ OK ☐ Not OK Check Charger for Defect ☐ OK ☐ Not OK Check Keyboard Casing ☐ OK ☐ Not OK Check Lan Connection ☐ OK ☐ Not OK Check battery life ☐ OK ☐ Not OK	
	Others:	
	Must bring this following tools to perform the Computer Preven Maintenance (CPM), the tools are screwdriver, brush, blower,	

crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.