COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature: JENVERIONES

Conducted by: ORVEINE PAUL ALMAGRO

Department: PRODUCTION CONTROL

PC no.: TEXC 0543

Factory no.: FACTORY 5

Date: 2023-07-19

Z	Clean	Dust	on CPU
M_ J	Olcaii	DUSEL	лгого

- ☑ Deleting Temp/Junk Files
- ☑ Antivirus Scan
- ☑ Disabling Hotspot
- ☑ Windows Update(Optional)
- □ Remove/Uninstall Unwanted Program

Check Monitor/Screen for Defect

☑ OK □Not OK

Check Charger for Defect

☑ OK □Not OK

Check Keyboard Casing

☑ OK □Not OK

Check Lan Connection

☑ OK □Not OK

Check battery life

☑ OK □Not OK

Others:

PASL 3

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

				Related Documents:	TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	RETENTION PERIOD
Efectivity Date:	2023-07-15	Prepared by	<i>'</i> :	Checked by: Approved by:	10 YEARS
		Rushky	Estrera	Rey Dagatan Amadito Ortizano	