GA Division	COMPUTER PREVENTIVE	TMF-G0054
ΙΤ	MAINTENANCE CHECKLIST	Version 1.00
User Signature Conducted by: Department:{ PC no.:\fractory no.:\fractory	TR-ANN ARRIBADO PR/SDGN O203 Nedical	2073 - 08 - DZ
☑ Deleti ☑ Antivi ☑ Disab ☑ Windo	Dust on CPU Ing Temp/Junk Files rus Scan ling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program	
Check (Check K	Monitor/Screen for Defect ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Ceyboard Casing ☐ OK ☐ Not OK an Connection ☐ OK ☐ Not OK eattery life ☐ OK ☐ Not OK	
Others:		
_	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, J45.	Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

*The user have to check and compare versions, effective date and sub master information before printing.