- 0

GA Division

COMPUTER PREVENTIVE MAINTENANCE CHECKLICT

TMF-G0054

IT	MAINTENANCE CHECKLIST	1	Version 1.00
User Signatur Conducted by Department:	TO-ANN ARRIBADO	Date: <u>१०७</u> ≉	- 07-27
PC no. : Factory no. :_			
☑ Delet ☑ Antiv ☑ Disab	n Dust on CPU ing Temp/Junk Files irus Scan oling Hotspot ows Update(Optional)		
	Monitor/Screen for Defect		
Check h	 ØK □Not OK Charger for Defect Ø OK □Not OK Keyboard Casing Ø OK □Not OK 		
	an Connection ☑ OK □Not OK pattery life ☑ OK □Not OK		
Others:			
eminders: Must bring this	s following tools to perform the Computer Preventive		

R

Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.