GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signature:		
☑ Delet ☑ Antivi ☑ Disab □ Wind	n Dust on CPU ing Temp/Junk Files irus Scan oling Hotspot ows Update( Optional ) ove/Uninstall Unwanted Program	
Check I Check L	Monitor/Screen for Defect  ☑ OK □Not OK Charger for Defect  ☑ OK □Not OK Keyboard Casing  ☑ OK □Not OK Lan Connection  ☑ OK □Not OK Dattery life  ☑ OK □Not OK	
Others:		
_	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, 1345.	Related Documents: TMF-G0058

<sup>\*</sup>It is permitted to use this form in both electronic and hard copy.

\*The user have to check and compare versions, effective date and sub master information before printing.