COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

	User Signature	A B1 (=0.0 A		ate: 2023 -07-18
	Conducted by:			
	Department: T			
PC no. : TFXC0654 Factory no. : FACTORY 2				
	ractory no. :	Thorony 2		
	☑ Clean	Dust on CPU		
	☑ Deletii	ng Temp/Junk Fi	les	
	☑ Antivir	rus Scan		
	☑ Disabl	ing Hotspot	•	
☑ Windows Update(Optional) ☑ Remove/Uninstall Unwanted Program				
Check Monitor/Screen for Defect				
☑ OK □Not OK				
Check Charger for Defect				
☑ OK □Not OK				
Check Keyboard Casing ☑ OK □Not OK				
Check Lan Connection				
Ø OK □Not OK				
Check battery life				
☑ OK ☐Not OK				
		-		
		<u> </u>		
	Others:			
]		
Reminders:				
Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser,				
crimper and RJ45.				
	Chinper and N	J45.		
···		· · · · · · · · · · · · · · · · · · ·	Related Docum	nents: TCF-G116
Document No:	TCF-G112	VER. 2	Toyoflex Cebu Corporat	ion RETENTION PERIOD
		Prepared by:	Checked by: Approved by:	
Efectivity Date:	2023-07-15	Rushky Estrera	Rey Dagatan Amadito O	10 YEARS