GA Division	COMPUTER PREVENTIVE	TMF-G0054
ΙΤ	MAINTENANCE CHECKLIST	Version 1.00
User Signature Conducted by Department:PC no. :Px	:	1023 ~ 07 - (
☑ Delet ☑ Antivi ☑ Disab □ Wind	n Dust on CPU ing Temp/Junk Files irus Scan pling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program	
Check I Check L	Monitor/Screen for Defect ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Ceyboard Casing ☐ OK ☐ Not OK Lan Connection ☐ OK ☐ Not OK Dattery life ☐ OK ☐ Not OK	
Others:		
	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, 8J45.	Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.