COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

| User Signature: Conducted by: Department: OA PUM PC no.: TEXCOULE FACTOR: 4A | Date: <u>ሎ የ ዓ - ም</u> - ፲୪ |
|---|-----------------------------|
| ☑ Clean Dust on CPU | |
| □ Deleting Temp/Junk Files | |
| ☑ Antivirus Scan | |
| ☑ Disabling Hotspot | |
| ☑ Windows Update(Optional) | |
| ☑ Remove/Uninstall Unwanted Program | |
| Check Monitor/Screen for Defect ☐ OK ☐ Not OK Check Charger for Defect ☐ OK ☐ Not OK Check Keyboard Casing ☐ OK ☐ Not OK Check Lan Connection ☐ OK ☐ Not OK Check battery life ☐ OK ☐ Not OK | |
| Others: | |

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

| | | - | | Related Documents: | TCF-G116 |
|-----------------------------|--------------|--------------|-----------------------------|---------------------------|------------------|
| Document No: | TCF-G112 | VER. | 2 | Toyoflex Cebu Corporation | RETENTION PERIOD |
| Efectivity Date: 2023-07-15 | Prepared by: | | Checked by: Approved by: | 10 YEARS | |
| | Rushky Est | rera | Rey Dagatan Amadito Ortizan | | |