GA Division	COMPUTER PREVENTIVE	TMF-G0054
ΙΤ	MAINTENANCE CHECKLIST	Version 1.00
User Signatur Conducted by Department: <u>Output</u> PC no. : <u>The Couper</u> Factory no. :_	Marto sarrosa	.023-08-15
r actory no	νγαιτοί	
☐ Clea	n Dust on CPU	
□ Dele	ing Temp/Junk Files	
	irus Scan	
	oling Hotspot	
	ows Update(Optional)	
□Rem	ove/Uninstall Unwanted Program	
Check I	Monitor/Screen for Defect	
	☑ OK □Not OK	
Check	Charger for Defect	
Chook	□ OK □Not OK	
Check	Keyboard Casing □ OK □Not OK	
Check I	an Connection	
2.,23,,	☑ OK □Not OK	
Check b	pattery life	
	☑ OK □Not OK	
Others:		

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.