GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signature:		
Department:	Wbbs	
PC no. : TEXCOULA		
Factory no.:		
	Durat are ODII	
☐ Clean Dust on CPU ☐ Deleting Temp/Junk Files		
☑ Antivirus Scan		
☐ Disabling Hotspot		
☑ Windows Update(Optional)		
☑ Remove/Uninstall Unwanted Program		
Check	Monitor/Screen for Defect ☑ OK □Not OK Charger for Defect ☑ OK □Not OK Keyboard Casing ☑ OK □Not OK	
Check Lan Connection		
☐ OK ☐ Not OK		
Check b	oattery life ☑ OK □Not OK	
Others:		
and the second of the second o	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, J45.	Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.
*The user have to check and compare versions, effective date and sub master information before printing.