COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

Date: 7013-07-17

User Signature:_

Conducted by. Foots of the Control		
Department: T-Assy / Packing of MCE		
PC no. : <u>TFXC0666</u>		
Factory no.: FACTORY 2		
☑ Clean Dust on CPU		
☑ Deleting Temp/Junk Files		
☑ Antivirus Scan		
☐ Disabling Hotspot		
/	•	
☑ Windows Update(Optional)		
☐ Remove/Uninstall Unwanted Program		
Chaple Manitar/Carana for Defeat		
Check Monitor/Screen for Defect		
□ OK □ Not OK	•	
Check Charger for Defect		
☑ OK □Not OK		
Check Keyboard Casing		
☐ OK ☐ Not OK		
Check Lan Connection	* ·	
☐ OK ☐ Not OK		
Check battery life		
☑ OK □Not OK		
Others: Level 2		
·		
Domindom		
Reminders:	or Droventive	
Must bring this following tools to perform the Compute		
Maintenance (CPM), the tools are screwdriver, brus	n, blower, eraser,	
crimper and RJ45.		
_		

2

Checked by:

Rey Dagatan

VER.
Prepared by:

Rushky Estrera

Document No:

Efectivity Date:

TCF-G112

2023-07-15

Related Documents:

Amadito Ortizano

Approved by:

Toyoflex Cebu Corporation

TCF-G116

RETENTION PERIOD

10 YEARS