## **COMPUTER PREVENTIVE MAINTENANCE CHECKLIST**

User Signature:  Conducted by:  Department:  OA Cards / NC  PC no.:  7 F X C 0 9 5 9  Factory no.:  Factory 3	Date: <u>1</u> ০১৭ -১৪~ 2৭
<ul> <li>☐ Clean Dust on CPU</li> <li>☐ Deleting Temp/Junk Files</li> <li>☐ Antivirus Scan</li> <li>☐ Disabling Hotspot</li> <li>☐ Windows Update( Optional )</li> <li>☐ Remove/Uninstall Unwanted Program</li> <li>Check Monitor/Screen for Defect</li> </ul>	
☑ OK □Not OK Check Charger for Defect ☑ OK □Not OK	
Check Keyboard Casing  ☑ OK □Not OK	
Check Lan Connection  ☐ OK ☐ Not OK ☐ OK ☐ OK ☐ OK ☐ Not OK	
☐ OK ☐ Not OK  Check battery life ☐ OK ☐ Not OK	
Others: Caids Common	

## Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents:					TCF-G116	
Document No:	TCF-G112	VER.	2	Toyoflex Cel	ou Corporation	RETENTION PERIOD
Efectivity Date: 2023-07-15	2023-07-15	Prepared by	:	Checked by:	Approved by:	40 VEADC
	Rushky	Estrera	Rey Dagatan	Amadito Ortizano	10 YEARS	