ń		
GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signature: Py: Conducted by: UNEULA MANNULLA Department: QA PC no.: TEXCOSOL Factory no.: MEDILIN FACTORY		: 197 - 59-34
□ Delet □ Antivi □ Disab □ Wind	n Dust on CPU ling Temp/Junk Files irus Scan oling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program	
Check Check K	Monitor/Screen for Defect ☑ OK ☐ Not OK Charger for Defect ☑ OK ☐ Not OK Keyboard Casing ☑ OK ☐ Not OK Lan Connection ☑ OK ☐ Not OK Dattery life ☑ OK ☐ Not OK	
Others:		
	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, J45.	, Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

*The user have to check and compare versions, effective date and sub master information before printing.