GA Division COMPUTER PREVENTIVE TMF-G0054 IT MAINTENANCE CHECKLIST Version 1.00 User Signature: Date: 2017 - 06-07 Conducted by: Mario carrosa Department: HR PC no.: TEXCOLOR Factory no. : Medical ☐ Clean Dust on CPU ☑ Deleting Temp/Junk Files ☑ Antivirus Scan ☑ Disabling Hotspot ☐ Windows Update(Optional) ☐ Remove/Uninstall Unwanted Program Check Monitor/Screen for Defect ☑ OK □ Not OK Check Charger for Defect ☑ OK □Not OK Check Keyboard Casing ☑ OK ☐ Not OK Check Lan Connection ☑ OK □Not OK Check battery life ☑ OK □Not OK Others:

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.