| t 0 | | |
|--|---|-----------------------------------|
| GA Division | COMPUTER PREVENTIVE | TMF-G0054 |
| IT | MAINTENANCE CHECKLIST | Version 1.00 |
| User Signature Conducted by: Department:_ PC no. : | HR/HR | e: |
| ☑ Deleti ☑ Antivi ☑ Disab □ Windo | Dust on CPU Ing Temp/Junk Files rus Scan ling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program | |
| Check (Check K | Monitor/Screen for Defect ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Ceyboard Casing ☐ OK ☐ Not OK an Connection ☐ OK ☐ Not OK attery life ☐ OK ☐ Not OK | |
| Others: | | |
| | s following tools to perform the Computer Preventive CPM), the tools are screwdriver, brush, blower, erase J45. | er, Related Documents: TMF-G0058 |

^{*}It is permitted to use this form in both electronic and hard copy.
*The user have to check and compare versions, effective date and sub master information before printing.