GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.0
User Signatu	ire: <u>Juinty from Date: 4</u>	023 - 08·D7
Conducted b		
Department:		
PC no. :	Texc 0895	
Factory no. :	Medical	
□ Clea	an Dust on CPU	
□ Dele	eting Temp/Junk Files	
☑ Anti	virus Scan	
Disa	bling Hotspot	
□ Win	dows Update(Optional)	
□ Rem	nove/Uninstall Unwanted Program	
Check	Monitor/Screen for Defect	
	☑ OK □Not OK	
Check	Charger for Defect	
	☐ OK ☐ Not OK	
Check	Keyboard Casing	
Ob a als	☑ OK □Not OK	
Cneck	Lan Connection	
Chack	□ OK □Not OK battery life	
Official	☑ OK □Not OK	
	Z OK LINGUOK	
Others	:	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and $\mathsf{RJ45}$.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.