-	n .				
GA	1)1	VI	SI	0	r

IT

COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

TMF-G0054

Version 1.00

User Signature: 444 Conducted by: 445 Department: 6A PC no.: 7FXC 05/64 Factory no.: Mcdical	Date: 2023 - 08 - 08
 □ Clean Dust on CPU □ Deleting Temp/Junk Files □ Antivirus Scan □ Disabling Hotspot □ Windows Update(Optional) □ Remove/Uninstall Unwanted Program 	
Check Monitor/Screen for Defect ☐ OK ☐ Not OK Check Charger for Defect ☐ OK ☐ Not OK Check Keyboard Casing ☐ OK ☐ Not OK Check Lan Connection ☐ OK ☐ Not OK Check battery life ☐ OK ☐ Not OK	
Others:	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.