GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signatur Conducted by	e: Da	te:_10 2 3- 0 841

Department: MPR0 PC no.: 1FXCUall Factory no. : Midical ☐ Clean Dust on CPU ☑ Deleting Temp/Junk Files ☑ Antivirus Scan ☑ Disabling Hotspot ☐ Windows Update(Optional) ☐ Remove/Uninstall Unwanted Program Check Monitor/Screen for Defect ☑ OK □Not OK Check Charger for Defect ☐ OK ☐ Not OK Check Keyboard Casing ☑ OK □Not OK Check Lan Connection ☐ OK ☐ Not OK Check battery life ☑ OK □ Not OK Others:

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.