GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signature Conducted by: Department: PC no.: TEXCED Factory no.: N	To-Ann Arribado  t  10	2027-07-31
<ul><li>☑ Deleti</li><li>☑ Antivir</li><li>☑ Disabl</li><li>☐ Windo</li></ul>	Dust on CPU ng Temp/Junk Files rus Scan ring Hotspot rws Update( Optional ) rve/Uninstall Unwanted Program	
Check C Check K Check La	onitor/Screen for Defect  ☑ OK □Not OK Charger for Defect  ☑ OK □Not OK eyboard Casing  ☑ OK □Not OK can Connection  ☑ OK □Not OK cattery life  ☑ OK □Not OK	
Others:		

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

<sup>\*</sup>It is permitted to use this form in both electronic and hard copy.
\*The user have to check and compare versions, effective date and sub master information before printing.