GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signature:  Conducted by:  Stella May 401 N  Department:  PC no.:  TEYC III  Factory no.:  WENCH FROM		
□ Delet ☑ Antivi ☑ Disab □ Wind	n Dust on CPU ing Temp/Junk Files irus Scan oling Hotspot ows Update( Optional ) ove/Uninstall Unwanted Program	
Check P Check L	Monitor/Screen for Defect  ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Keyboard Casing ☐ OK ☐ Not OK Lan Connection ☐ OK ☐ Not OK Dattery life ☐ OK ☐ Not OK	
Others:		
, — , , — , , — , , — , , — , , — , , — , , — , , — , , — , , — , , — , , — , , — , , — , , — , , — , , — , ,	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, J45.	Related Documents: TMF-G0058

<sup>\*</sup>It is permitted to use this form in both electronic and hard copy.

<sup>\*</sup>The user have to check and compare versions, effective date and sub master information before printing.