COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature:	Date: <u> ℓ∞</u> ₃ -0ఽ -0 ६
Conducted by: ORVEINE PAUL ALMAGRO	
Department: GX-QC	
PC no. : 1FXC0814	
Factory no.: 5/Cto2y '	
<u> </u>	
☑ Clean Dust on CPU	
☑ Deleting Temp/Junk Files	
☑ Antivirus Scan	
☑ Disabling Hotspot	
☑ Windows Update(Optiona	al)
☑ Remove/Uninstall Unwant	•
E Remove/Offinstall Offwart	ed Frogram
Check Monitor/Screen for De	efect
☑ OK □Not O	
Check Charger for Defect	
☑ OK □Not O	V.
Check Keyboard Casing	
☑ OK □Not O	V.
Check Lan Connection	
	V
☑ OK □Not O	N.
Check battery life	
☑ OK □Not O	X.
Others: PASL 3	
PSL 3	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

				Related Docu	ments:	TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation		RETENTION PERIOD
Efectivity Date: 2023-07-15	Prepared by		Checked by: Approved by:		10 YEARS	
		Rushky	Estrera	Rey Dagatan Amadito C	ntizano	<u></u>