| GA Division | COMPUTER PREVENTIVE | TMF-G0054 |
|--|---|----------------------------------|
| IT | MAINTENANCE CHECKLIST | Version 1.00 |
| User Signature Conducted by Department:_ PC no. :_ 1+x0 Factory no. :_1 | DE D | ate:_ <u>& 128 ~ 07 - 31</u> |
| DeletAntiviDisabWindRemo | n Dust on CPU ing Temp/Junk Files rus Scan bling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program Monitor/Screen for Defect | |
| Check k | | |
| Check b | ☑ OK □Not OK pattery life ☑ OK □Not OK | |
| Others: | | |
| eminders: | | |

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.