COMPUTER PREVENTIVE GA Division IT

MAINTENANCE CHECKLIST

TM	F-	GO	054	1
1 1 7 1		\circ	05-	т -

Version 1.00

User Signature: Conducted by: Mario Sarroga Department: PE PC no.: Texcusor Factory no.: Midical	Date: 2025-08-24
 □ Clean Dust on CPU ☑ Deleting Temp/Junk Files ☑ Antivirus Scan ☑ Disabling Hotspot □ Windows Update(Optional) □ Remove/Uninstall Unwanted Program 	
Check Monitor/Screen for Defect ☐ OK ☐ Not OK Check Charger for Defect ☐ OK ☐ Not OK Check Keyboard Casing ☐ OK ☐ Not OK Check Lan Connection ☐ OK ☐ Not OK Check battery life ☐ OK ☐ Not OK	
Others:	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.