COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature: Conducted by: ORVEINE PAUL ALMAGRO Department: WE NYLON COATING PC no.: TFX coe 40 Factory no.: Ff-ctor-> /	Date: <u>/</u> 2023 - 0 <u>ያ</u> - <u>୬</u> ብ
 ☑ Clean Dust on CPU ☑ Deleting Temp/Junk Files ☑ Antivirus Scan ☑ Disabling Hotspot ☑ Windows Update(Optional) ☑ Remove/Uninstall Unwanted Program 	
Check Monitor/Screen for Defect ☐ OK ☐ Not OK Check Charger for Defect ☐ OK ☐ Not OK Check Keyboard Casing ☐ OK ☐ Not OK Check Lan Connection ☐ OK ☐ Not OK Check battery life ☐ OK ☐ Not OK	
Others: PASL 3	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

	-			Related Documents	: TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	RETENTION PERIOD
Efectivity Date: 2023-07-15	Prepared by	:	Checked by: Approved by:	10 YEARS	
	Rushky	Estrera	Rey Dagatan Amadito Ortizan		