## **COMPUTER PREVENTIVE MAINTENANCE CHECKLIST**

User Signature: ANTAZURITA	Date: 2023-07-2
Conducted by: ORVEINE PAUL ALMAGRO	
Department: SPRING COIL	
PC no. :_ 1FXC5885	•
Factory no.: FACTORY 6	
☑ Clean Dust on CPU	
☑ Deleting Temp/Junk Files	
☑ Antivirus Scan	
☑ Disabling Hotspot	
☑ Windows Update( Optional )	
Check Monitor/Screen for Defect	
☑ OK □Not OK	
Check Charger for Defect	
☑ OK □Not OK	
© OK □Not OK  Check Keyboard Casing	
☑ OK □Not OK	
Check Lan Connection	
☑ OK □Not OK	
Check battery life	
✓ OK □Not OK	
M OK LINULOR	
Oth sures	<del></del> 1
Others:	
PXSL 3	

## Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

				Related Documents	:: TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	RETENTION PERIOD
Efectivity Date:	Prepared by: 2023-07-15 Rushky Estrera	Prepared by:		Checked by: Approved by:	10 YEARS
		strera	Rey Dagatan Amadito Ortizar		