GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signature Conducted by Department:_ PC no. : Factory no. :	TARER TEXCOLUP	NN4 - 29- 04
☑ Deleti ☑ Antivi ☑ Disab ☑ Winde	n Dust on CPU ing Temp/Junk Files rus Scan bling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program	
Check (Check K	Monitor/Screen for Defect ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Ceyboard Casing ☐ OK ☐ Not OK can Connection ☐ OK ☐ Not OK cattery life ☐ OK ☐ Not OK	
Others:		
	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, J45.	Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

*The user have to check and compare versions, effective date and sub master information before printing.