COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature: Single Ames Dutekte Conducted by: PODE Ames Dutekte Department: GA-Or / Incoming PC no.: TEx C 0344 Factory no.: Factory 5	Date: <u>2003</u> - 0 > - 1 >
☐ Clean Dust on CPU ☐ Deleting Temp/Junk Files ☐ Antivirus Scan ☐ Disabling Hotspot ☐ Windows Update(Optional) ☐ Remove/Uninstall Unwanted Program	
Check Monitor/Screen for Defect ☐ OK ☐ Not OK Check Charger for Defect /// ☐ OK ☐ Not OK Check Keyboard Casing ☐ OK ☐ Not OK Check Lan Connection ☐ OK ☐ Not OK Check battery life /// ☐ OK ☐ Not OK	
Others: Caids Incoming	

Reminders:

must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

					Related Documents:	TFJ-S16-G008
Document No: TCF-G11		VER.	2	Toyoflex C	ebu Corporation	RETENTION PERIOD
		Prepared by: Rushky Estrera		Checked by:	Approved by:	· · · · · · · · · · · · · · · · · · ·
Efectivity Date:	2023-07-15			Rey Dagatan	Amadito Ortizano	10 YEARS