COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

\bigcap	
User Signature:	Date: <u> </u>
Conducted by: KNAVERPJADE PARAN	
Department: HR	
PC no.: 1FKC W89	
Factory no.: Pactry	
EX Class Dust as ODE	
☑ Clean Dust on CPU	
☑ Deleting Temp/Junk Files	
☑ Antivirus Scan	
☑ Disabling Hotspot	
☑ Windows Update(Optional)	
□ Remove/Uninstall Unwanted Program	
Check Monitor/Screen for Defect	
□ OK □Not OK	
Check Charger for Defect	
□ OK □Not OK	
Check Keyboard Casing	
☐ OK ☐ Not OK	
Check Lan Connection	
☑ OK □Not OK	
Check battery life	
☑ OK □Not OK	
Others:	
Pas 3	
12013	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

					Related Documents:	TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation		RETENTION PERIOD
Efectivity Date: 2	2023-07-15	Prepared by: Checked by:		Approved by:	10 YEARS	
		Rushky E	strera	Rey Dagatan	Amadito Ortizano	10 TEARS