g	1	
GA Division	COMPUTER PREVENTIVE	TMF-G0054
ΙΤ	MAINTENANCE CHECKLIST	Version 1.00
User Signatur Conducted by Department:_ PC no. :15X0 Factory no. :_	PR/PS/PE	2023 - 09 - 19
☑ Delet ☑ Antiv ☑ Disat □ Wind	n Dust on CPU ing Temp/Junk Files irus Scan oling Hotspot ows Update( Optional ) ove/Uninstall Unwanted Program	
Check I Check I	Monitor/Screen for Defect  ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Keyboard Casing ☐ OK ☐ Not OK Lan Connection ☐ OK ☐ Not OK Dattery life ☐ OK ☐ Not OK	
Others:		
eminders:	s following tools to perform the Computer Preventive	

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

<sup>\*</sup>It is permitted to use this form in both electronic and hard copy.

<sup>\*</sup>The user have to check and compare versions, effective date and sub master information before printing.