## COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature: Otwoor	Date:
Conducted by: Swette JURBAND	
Department: WR- SUPPORT GROUP	
PC no. : 1F+C1003	
Factory no.: FACTOR + 3	
☑ Clean Dust on CPU	
☑ Deleting Temp/Junk Files	
☑ Antivirus Scan	
☑ Disabling Hotspot	
☑ Windows Update( Optional )	
☑ Remove/Uninstall Unwanted Program	
Check Monitor/Screen for Defect  ☑ OK ☐ Not OK Check Charger for Defect ☑ OK ☐ Not OK Check Keyboard Casing ☑ OK ☐ Not OK Check Lan Connection ☑ OK ☐ Not OK Check battery life ☑ OK ☐ Not OK	
Others:	

## Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance ( CPM ), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

			Related Documents:		TCF-G116	
Document No:	TCF-G112	VER.	2	Toyoflex Ce	bu Corporation	RETENTION PERIOD
		Prepared by:		Checked by:	Approved by:	
Efectivity Date:	2023-07-15	Rushky E	strera	Rey Dagatan	Amadito Ortizano	10 YEARS