GA Division	COMPUTER PREVENTIVE	TMF-G0054
ΙΤ	MAINTENANCE CHECKLIST	Version 1.00
_,,		l
User Signature: Date: 2021 - 08 - 30		
Conducted by:		
Conducted by: Department: QA/Qx		
PC no.: t	XC Dee Dale c	
	Medica	
	<u> </u>	
☑ Clean Dust on CPU		
☐ Deleting Temp/Junk Files		
☑ Antivirus Scan		
☐ Disabling Hotspot		
☐ Windows Update(Optional)		
☐ Remove/Uninstall Unwanted Program		
Check Monitor/Screen for Defect		
☐ OK ☐ Not OK		
Check Charger for Defect		
□ OK □Not OK		
Check Keyboard Casing		
	Ø OK □Not OK	
Check Lan Connection		
☑ OK □Not OK		
Check battery life		
	☑ OK □Not OK	
Others:		
outers.		
Developed		
Reminders:		
Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser,		
crimper and R		,
onimpor and Ne		Related Documents: TMF-G0058
		Heldica pocalitetita: HAIL-20030

^{*}It is permitted to use this form in both electronic and hard copy.
*The user have to check and compare versions, effective date and sub master information before printing.