CA Division	COMPUTED DDEXTENTING	
GA Division COMPUTER PREVENTIVE		TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
	SHELLY MALINGIN	
☑ Clean Dust on CPU		
☑ Deleting Temp/Junk Files		
☐ Antivirus Scan		
☑ Disabling Hotspot☑ Windows Update(Optional)		
☐ Remove/Uninstall Unwanted Program		
Check Check K	Monitor/Screen for Defect ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Geyboard Casing ☐ OK ☐ Not OK can Connection ☐ OK ☐ Not OK cattery life ☐ OK ☐ Not OK	
Others:		
	s following tools to perform the Computer Preventive CPM), the tools are screwdriver, brush, blower, eraser, J45.	Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.