COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

User Signature:	Date: 2023-07-19
Conducted by: ORVEINE PAUL ALMAGRO	Date. 2020 VI 11
Department: PRDD WOTION CONTROL	
PC no. : 1FX CO 547	
Factory no. :_ FACTORY 5	
-	
☑ Clean Dust on CPU	
☑ Deleting Temp/Junk Files ☑ Antivirus Scan	
☑ Disabling Hotspot	
☑ Windows Update(Optional)	
☑ Remove/Uninstall Unwanted Program	
Check Monitor/Screen for Defect	
☐ OK ☐ Not OK	
Check Charger for Defect	
☑ OK □Not OK	
Check Keyboard Casing	
☑ OK □Not OK	
Check Lan Connection	
☑ OK □Not OK	
Check battery life	
☑ OK □Not OK	
Others: TKSL3	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

				Related Documents:	TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	RETENTION PERIOD
Efectivity Date: 2023-07-15	2023-07-15	Prepared by	' :	Checked by: Approved by:	10 YEARS
		Rushky	Estrera	Rey Dagatan Amadito Ortizano	