GA Division	COMPUTER PREVENTIVE	TMF-G0054
IT	MAINTENANCE CHECKLIST	Version 1.00
User Signature Conducted by: Department: PC no. : Factory no. :	PE PKCO 806	993 · 08 - 07
☑ Deletir☑ Antivir☑ Disabli☐ Windo	Dust on CPU ng Temp/Junk Files us Scan ng Hotspot ws Update(Optional) ve/Uninstall Unwanted Program	
Check C	onitor/Screen for Defect ☐ OK ☐ Not OK harger for Defect ☐ OK ☐ Not OK eyboard Casing ☐ OK ☐ Not OK on Connection ☐ OK ☐ Not OK ttery life ☐ OK ☐ Not OK	
Others:		

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.