GA Division	COMPUTER PREVENTIVE	TMF-G0054
ΙΤ	MAINTENANCE CHECKLIST	
Conducted by Department: 4 PC no. : TFx 6 0 Factory no. : N	: Mario sarrosa A/urility 165 Midical	<u>123-08-05</u>
☑ Delet ☑ Antiv ☑ Disab □ Wind	n Dust on CPU ing Temp/Junk Files rus Scan pling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program	
Check Check L	Monitor/Screen for Defect ☐ OK ☐ Not OK Charger for Defect ☐ OK ☐ Not OK Keyboard Casing ☐ OK ☐ Not OK Lan Connection ☐ OK ☐ Not OK Dattery life ☐ OK ☐ Not OK	
Others:		
	s following tools to perform the Computer Preventive (CPM), the tools are screwdriver, brush, blower, eraser, RJ45.	Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.
*The user have to check and compare versions, effective date and sub master information before printing.