COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

Superdand

User Signature:	Date: 1024 -09 -29
Conducted by: KNAVEN JADE PARAN	
Department: 역 (의상 / // C .	
PC no.: (Eaching 3) TEXC 0969	
Factory no.: factory 3	
1 J	
☑ Clean Dust on CPU	
□ Deleting Temp/Junk Files	
☑ Disabling Hotspot	
Windows Update(Optional)	
☐ Remove/Uninstall Unwanted Program	
Check Monitor/Screen for Defect	
☐ OK ☐ Not OK	
Check Charger for Defect	
□ OK □Not OK	
Check Keyboard Casing	
☐ OK ☐ Not OK	
Check Lan Connection	
□ OK □Not OK	
Check battery life	
□ OK □Not OK	
Others:	
Official.	
Reminders:	
Must bring this following tools to perform the Compu	
Maintenance (CPM), the tools are screwdriver, bru	sh, blower, eraser,

				Related Documents:	TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corporation	RETENTION PERIOD
		Prepared by:		Checked by: Approved by:	
Efectivity Date:	2023-07-15	Rushky E	Estrera	Rey Dagatan Amadito Ortizano	10 YEARS

crimper and RJ45.